

Master List of General ACM Locations

Revision Date: **11/30/2016**

Schools	Tunnels			Ceiling Plenum ²			Ceiling			Walls			Doors		Floors	Boiler/Mech Rooms			Roof			Fixtures
	TSI-Fittings	TSI-Sealant	TSI-Contam.	Surfacing	TSI-Fittings	TSI-Sealant	Surfacing	Tile	Joint Compound	Joint Compound	Transite	CMU	Fire Doors	Non-Rated	Floor Tile ¹	TSI-Fitting	TSI-Sealant	Misc.	Flashing	Felt	Misc.	Misc.
Elementary Schools																						
Altura												Trace			X				X			Win. Caulking, wall adhesive
Arkansas						X									X		X	Gaskets				Cove base
Boston	No ACM present in building																					
Century	No ACM present in building																					
Clyde Miller															X				Pitch Pan Tar			Covebase '84 Addition
Crawford					X	X									X		X		X	X		Covebase adhesive
Dalton				Hangar Adhesive		X									X		X					Covebase adhesive
Dartmouth									X	X					X							
Elkhart													X	X	X			skimcoat				Counters & Win caulk
Fletcher	No ACM Present in Building																					
Fulton			X	X					X	TSI in Walls/Chases			X		X, X ³							
Iowa	No ACM Present In Building																					
Jamaica							Wall/ceiling overspray			X	TSI in Walls/Chases				X, X ³							Pipe ins in slab
Jewell															X							
Kenton	X		X										X		X ³ -no ft				X	X		Ext Win caulk
Lansing			X												X, X ³							Faculty RR -TSI in walls
Lansing Mobile 0010															X							
Laredo										X					X				X			
Lyn Knoll				Vibration Dampers				stage					X	X	X							win caulk
Montview			X	X	X		X (Second Ceiling)			Plaster			X		X, X ³			Gasket				Exterior overhang
Montview Mobile 0013												Exterior			X							
Paris	No ACM present in building																					
Park Lane															X, X ³				X		X	
Peoria Elem (old Wm. Smith H.S.)				encapsulated								old office area			X ³				X	X		TSI fittings
Sable			X									Exterior	X		X				X			TSI fittings
Side Creek	No ACM Present In Building																					
Sixth Avenue			X				plaster				Plaster, Black Adhesive				X, X ³				X	X		win & block caulk
Tollgate									X		wallpaper adhesive											
Vassar						TSI & Duct sealant									X		X & Duct sealant					
Vaughn	X		X												X, X ³				X	X		
Virginia Court									Trace	Trace		X			X				X			TSI fittings
Wheeling				X	X		Gym second ceiling			TSI in Walls/Chases			X		X			walls				
Yale															X				X			Cove Base
Middle Schools																						
Aurora Hills	No ACM Present In Building																					
Aurora Frontier K-8	No ACM Present In Building																					
Quest Academy	No ACM Present In Building																					
Columbia												Exterior			X							Counters, cb adhesive
East					X	X	Soffit, Stage-vibration dampers	X	CT/stage	vermiculite in walls	X				X		X	Boiler brick				Countertops
Mrachek						X 1st Fl.							X		X				X			Countertops
Murphy Creek K-8	No ACM Present In Building																					
North	X			Exposed Gym				Plaster	Plaster				X		X, X ³							Brown wall adhesive
South	cat walk			X above drop in media	X										X				X			
West			X								TSI in Walls/Chases		X		X, X ³				X			Stage lighting

Schools	Tunnels			Ceiling Plenum ²			Ceiling			Walls			Doors		Floors	Boiler/Mech Rooms			Roof			Fixtures		
	TSI-Fittings	TSI-Sealant	TSI-Contam.	Surfacing	TSI-Fittings	TSI-Sealant	Surfacing	Tile	Joint Compound	Joint Compound	Transite	CMU	Fire Doors	Non-Rated	Floor Tile ¹	TSI-Fitting	TSI-Sealant	Misc.	Flashing	Felt	Misc.	Misc.		
High Schools																								
Aurora Central				Air cell pipe insulation 400 hallway, TSI contamination						plaster												X	Gasket	Pipe Insulation in walls
Gateway			X			X	X						X, Surfacing in cavities		X								Gasket	Countertops
Hinkley		under gym only			Fireproofing, Vib damp	X				Plaster	Int./Ext.											X	Gasket	
Hinkley District Stadium													in pressbox											
Rangeview						X									X		X	RTUs?	X					Countertops and hoods
T.H. Pickens Bldg. A				In block walls	X					Overspray Kitchen walls		X							X		X			
T.H. Pickens Bldg. B												X			X				X					
T.H. Pickens Bldg. C										X		X							X					
T.H. Pickens Bldg. D						X						X			X				X					
T.H. Pickens Mobile 0037											Exterior													
William Smith High School	No ACM present in building																							
Other Locations																								
Education Svc 4 (Admin)					X		Stairwell		Trace	Trace & TSI in walls	Exterior				X				X					Win. Caulking, ceiling ins in boiler rm
Aurora Academy Charter	No responsibility																							
IT Center	No ACM Present in Building																							
Education Svc 3 (CentreTech)	No ACM Present In Building																							
Child Development Center	No ACM Present In Building																							
Driver Education	No ACM Present In Building																							
Facilities (Construction. Mgmt)										possible					X									
Facilities (North Barracks)	Building demolished 2012																							
Facilities Mobile 0041															X									
Education Svc 2 (Hline A)					X																			
Education Svc 1(Hline B)															Mastic							Caulking Paste on Units		Baseboard adhesive
Meadowood CDC	No ACM Present In Building																							
Montview Annex (Cont. Ed.)	Contaminated Soil				X										X			Joint Compound						Ext. Window Putty
Laredo Annex	Building demolished																							
Transportation	No ACM Present In Building																							
Transportation Administration	No ACM Present In Building																							
Warehouse															X							Caulking	Pitch Pan Tar	

TSI = Thermal Systems Insulation
Sealant = Fiberglass Sealant
1 Floor Tile may also be located beneath existing carpet ^ May include vinyl stair tread
2 If ceiling plenum contains surfacing, do not disturb or access through lower ceiling.
3 Surfacing contamination between finished floor and wood sub-floor.