

# General ACM Locations for Team A

Revision Date: 11/30/2016

Elementary Schools	Tunnels			Ceiling Plenum <sup>2</sup>			Ceiling			Walls			Doors		Floors	Boiler Room			Roof			Fixtures
	TSI-Fittings	TSI-Sealant	TSI-Contam.	Surfacing	TSI-Fittings	TSI-Sealant	Surfacing	Tile	Joint Compound	Joint Compound	Transite	CMU	Fire Doors	Non-Rated	Floor Tile <sup>1</sup>	TSI-Fitting	TSI-Sealant	Misc.	Flashing	Felt	Misc.	Counter Tops
Altura												Trace			X				X			Win. Caulking, wall adhesive
Boston	No ACM present in building																					
Crawford					X	X									X		X		X	X		base adhesive
Fletcher	No ACM Present in Building																					
Fulton			X	X					X			TSI in Walls/Chases		X		X, X3						
Jamaica			Gym only				Wall/ceiling overspray				X	TSI in Walls/Chases				X, X3						Pipe ins in slab
Kenton	X		X											X		X3-no ft				X	X	Ext Win caulking
Lansing			X													X, X3						Faculty RR - TSI in walls
Lansing Mobile 0010																X						
Laredo												X				X			X			
Lyn Knoll							Vibration Dampers		stage					X	X	X						win caulking
Montview			X	X	X			X (Second Ceiling)				Plaster		X		X, X3			Gasket			exterior overhang
Montview Mobile 0013												Exterior				X						
Paris	No ACM present in building																					
Park Lane																X, X3				X		X
Peoria Elem (old Wm. Smith H.S.)			encapsulate									old office area				X3				X	X	TSI fittings
Sable			X									Exterior		X		X				X		TSI fittings
Sixth Avenue			X				plaster					Plaster, Black Adhesive				X, X3				X	X	win & block caulking
Vaughn	X		X													X, X3				X	X	
<b>Middle Schools</b>																						
North	X					Exposed Gym			Plaster		Plaster			X		X, X3						down wall adhesive
South	cat walk					ve drop in	X									X				X		
West			X									TSI in Walls/Chases		X		X, X3				X		Stage lighting
<b>High Schools</b>																						
Aurora Central	insulation 400 hallway, TSI		X				plaster				overspray, Vermiculite in walls, plaster		X					X	Gasket			Pipe Insulation in
<b>Other Locations</b>																						
Education Svc Center (Admin)					X		Stairwell		Trace		Trace & TSI in	Exterior				X				X		Win. Caulking, ceiling ins in boiler rm
Child Development Center	No ACM Present In Building																					
Laredo Annex	Building demolished																					
Montview Annex (Cont. Ed.)	Contaminated Soil				X											X			Joint Compound			Ext. Window Putty
Intercept Center	#REF!																					

**TSI** = Thermal Systems Insulation  
**Sealant** = Fiberglass Sealant

<sup>1</sup> Floor Tile may also be located beneath existing carpet / May include vinyl stair tread

<sup>2</sup> If ceiling plenum contains surfacing, do not disturb or access through lower ceiling.

<sup>3</sup> Surfacing contamination between finished floor and wood sub-floor.