

Radon test result report for:**ESC 4****ESC 4**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7885481	100	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	1.0 ± 0.3	2017-06-10
7885490	100 DUP	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	1.0 ± 0.2	2017-06-10
7885491	100A	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	1.1 ± 0.2	2017-06-10
7885492	101	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	2.0 ± 0.3	2017-06-10
7885493	102	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	1.9 ± 0.3	2017-06-10
7885495	103	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	1.9 ± 0.3	2017-06-10
7885496	104	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	1.1 ± 0.3	2017-06-10
7885497	104 A	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	1.0 ± 0.3	2017-06-10
7885511	106	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.6 ± 0.2	2017-06-10
7885510	108	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.7 ± 0.2	2017-06-10
7885509	109	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	1.1 ± 0.2	2017-06-10
7885508	109 A	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	1.4 ± 0.3	2017-06-10
7885502	110	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.7 ± 0.2	2017-06-10
7885507	110 A	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	1.2 ± 0.3	2017-06-10
7885506	110 B	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.7 ± 0.2	2017-06-10
7885505	110 C	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885504	110 D	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.7 ± 0.2	2017-06-10
7885503	110 E	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.8 ± 0.2	2017-06-10
7885500	111	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.7 ± 0.2	2017-06-10
7885501	111 DUP	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.6 ± 0.2	2017-06-10
7885494	113 LOUNGE	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	1.2 ± 0.3	2017-06-10
7885480	115	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	2.1 ± 0.3	2017-06-10
7885488	116	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	0.9 ± 0.2	2017-06-10
7885487	117	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	1.1 ± 0.2	2017-06-10
7885484	118	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	1.2 ± 0.2	2017-06-10
7885483	119	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885489	123	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	0.8 ± 0.2	2017-06-10
7885482	124	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	0.8 ± 0.2	2017-06-10
7885486	125	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	1.3 ± 0.3	2017-06-10
7885522	BLANK	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885521	BLANK	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885498	BOARD RM E	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885499	BOARD RM W	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885519	C.A. LOUNGE	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885520	C.A. LOUNGE DUP	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885515	C.A. NW	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.5 ± 0.2	2017-06-10
7885518	C.A. OFF	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10

June 12, 2017

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

ESC 4

ESC 4

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7885516	C.A. SW	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885514	CENTRAL ADMIN	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.5 ± 0.2	2017-06-10
7885512	CONF C EAST	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	< 0.3	2017-06-10
7885513	CONF C WEST	2017-06-06 @ 8:00 am	2017-06-08 @ 8:00 am	0.9 ± 0.2	2017-06-10
7885485	RECEPTION	2017-06-06 @ 7:00 am	2017-06-08 @ 8:00 am	0.8 ± 0.2	2017-06-10

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498