

Radon test result report for:**JAMAICA
JAMAICA**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7158759	1	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	2.0 ± 0.3	2017-04-08
7158752	A1	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.3 ± 0.3	2017-04-08
7158757	A4	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	2.1 ± 0.3	2017-04-08
7158746	A4 DUP	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	2.6 ± 0.4	2017-04-08
7158740	BLANK	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	< 0.3	2017-04-08
7158758	C2	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.7 ± 0.3	2017-04-08
7158756	C3	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.4 ± 0.3	2017-04-08
7158755	C4	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.6 ± 0.3	2017-04-08
7158750	C5	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.3 ± 0.3	2017-04-08
7158741	C5 DUP	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.4 ± 0.3	2017-04-08
7158748	C6	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.3 ± 0.3	2017-04-08
7158749	C7	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.7 ± 0.3	2017-04-08
7158747	C8	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.8 ± 0.3	2017-04-08
7158753	CLINIC	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.3 ± 0.3	2017-04-08
7158743	CUSTODIAL OFFICE	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.3 ± 0.3	2017-04-08
7158744	G1	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.3 ± 0.3	2017-04-08
7158745	G2	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.6 ± 0.3	2017-04-08
7158742	KITCHEN	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	0.9 ± 0.3	2017-04-08
7158751	LOUNGE	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	2.8 ± 0.4	2017-04-08
7158754	PRIN	2017-04-03 @ 8:00 am	2017-04-05 @ 8:00 am	1.5 ± 0.3	2017-04-08