

May 22, 2017

**\*\* LABORATORY ANALYSIS REPORT \*\***

Radon test result report for:

**GARAGE  
TRANSPO GARAGE**

<b>Kit #</b>	<b>Room Id</b>	<b>Started</b>	<b>Ended</b>	<b>pCi/L</b>	<b>Analyzed</b>
7886485	BLANK	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	< 0.3	2017-05-22
7886490	BREAK RM	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	1.7 ± 0.5	2017-05-22
7886476	PARTS OFF	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	2.2 ± 0.5	2017-05-22
7886487	PURCH OFF	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	1.2 ± 0.4	2017-05-22
7886486	RECEPTION	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	1.5 ± 0.4	2017-05-22
7886479	SHOP 1	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	0.9 ± 0.4	2017-05-22
7886480	SHOP 2	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	1.0 ± 0.5	2017-05-22
7886481	SHOP 3	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	0.7 ± 0.4	2017-05-22
7886482	SHOP 4	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	0.9 ± 0.5	2017-05-22
7886483	SHOP 5	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	1.1 ± 0.4	2017-05-22
7886484	SHOP 6	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	2.5 ± 0.5	2017-05-22
7886489	SHOP FOREMAN	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	1.4 ± 0.5	2017-05-22
7886488	SUPERVISOR OFF	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	1.1 ± 0.4	2017-05-22
7886478	UOHOLSTRY OFF DU	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	2.0 ± 0.5	2017-05-22
7886477	UPHOLSTRY OFF	2017-05-15 @ 9:00 am	2017-05-17 @ 11:00 am	1.4 ± 0.4	2017-05-22