

## COMMERCIAL RADON REPORT

Date: 11/14/12

Page: 1 of 85

**School District:** Aurora Public Schools  
**Address:** 1369 Airport Boulevard  
Aurora, Colorado 80011  
**Attention:** Environmental Compliance  
**Call** (303)367-3000 ext. 28681

Canisters placed at **Aurora Hills Ms**, 1009 S. Uvalda St, Aurora, CO 80012

Canister #	Location	Radon Level(pCi/L)
65079	E142	1.01 ± 0.25
65104	E141	1.15 ± 0.26
65117	C161	1.06 ± 0.20
65100	B162 Office	0.98 ± 0.20
65121	C162	1.22 ± 0.20
65102	Gym 1	1.03 ± 0.26
65063	Gym 2	0.55 ± 0.20
65130	G114 LR Girls	0.68 ± 0.20
65048	G111 LR Boys	1.31 ± 0.26
65059	B113 Gym Office	0.93 ± 0.25
65080	B112 Gym Office	1.20 ± 0.26
65118	Stage	1.16 ± 0.26
65126	G115 Fitness	0.70 ± 0.20
65076	Commons 1	0.92 ± 0.20
65127	Commons 2	1.14 ± 0.20
65134	Commons 2 - Dup	1.17 ± 0.26
65109	Kitchen	0.99 ± 0.25
65131	Kitchen Office	0.80 ± 0.26
65135	Custodial Office	2.04 ± 0.27
65086	Custodial Office - Dup	2.01 ± 0.20
65071	D162	1.29 ± 0.20

65398	Blank	-0.08 ± 0.18
65407	Blank	0.36 ± 0.24
65142	C123	1.36 ± 0.17
65094	D123 - Media	0.75 ± 0.16
65088	C122	1.75 ± 0.22
65115	C121	1.18 ± 0.17
65106	C120	1.02 ± 0.22
65107	E120	0.65 ± 0.22
65120	E131	1.68 ± 0.26
65099	C135	1.18 ± 0.26
65125	C135 - Prep	1.57 ± 0.20
65113	C134	0.58 ± 0.22
65066	C133	0.80 ± 0.20
65093	D133 - Media	0.74 ± 0.22
65122	C132	1.51 ± 0.26
65074	C131	0.86 ± 0.17
65124	C130	1.06 ± 0.25
65110	C130 - Dup	0.63 ± 0.19
65116	E130	0.70 ± 0.19
65046	C141 - Comp Lab	1.30 ± 0.25
65087	L141	1.04 ± 0.20
65085	C118 - Art Office	0.84 ± 0.17
65090	B117 - ESS Office	0.78 ± 0.20
65075	C117	1.03 ± 0.26
65140	C116	1.25 ± 0.20
65054	E111	1.33 ± 0.17
65062	C115	1.28 ± 0.26
65067	C115 - Prep	0.54 ± 0.22
65139	C114	1.42 ± 0.22
65053	C113	1.25 ± 0.17
65084	D113 - Media	0.69 ± 0.22
65137	C112	1.07 ± 0.22
65133	C111	1.69 ± 0.22

65070	C110	1.49 ± 0.22
65119	E110	0.76 ± 0.17
65050	C125 - Prep	0.82 ± 0.22
65081	E121	1.10 ± 0.17
65083	E121 - Dup	1.25 ± 0.17
65112	C125	0.73 ± 0.16
65105	C124	0.96 ± 0.17
65101	A101 - Reception	0.74 ± 0.17
65123	A119 - Clinic	1.32 ± 0.26
65056	Clinic Office	1.03 ± 0.20
65045	A102	1.12 ± 0.17
65141	A103	2.33 ± 0.26
65073	A104	1.15 ± 0.22
65129	A105	1.22 ± 0.23
65057	A106	0.97 ± 0.22
65051	A107	0.96 ± 0.17
65068	A108	0.09 ± 0.24
65143	A109	0.89 ± 0.25
65111	A110	0.60 ± 0.20
65052	A111	0.69 ± 0.17
65132	A112	0.96 ± 0.17
65047	A113	0.79 ± 0.22
65064	A114	1.06 ± 0.22
65055	A115	0.48 ± 0.22
65049	A116	0.94 ± 0.17
65061	A117	0.98 ± 0.20
65108	A118	1.02 ± 0.22
65058	A118 Dup	0.93 ± 0.22
65128	C118 - Art	0.65 ± 0.24

Since our laboratory does not place the canisters nor monitor the conditions and the time under which the canister is exposed, we are unable to guarantee the integrity of any part of the testing procedure except for that portion for which we are directly responsible; the handling and quality assurance procedures of the canisters up until the time they leave our lab and the accuracy (within statistically imposed limits) of the actual measuring process in our lab.

E- Mail Date: 11/14/12

By: Thomas Brown

---

RADON Measurements Lab, 1420 Austin Bluffs Parkway, UCCS Engineering Building  
Room 215, Colorado Springs, CO 80918