

Radon Environmental Monitoring (ESG)
3334 Commercial Avenue
Northbrook, IL 60062 USA
(847) 205-0110

Mark Davis / Beth Davis
 Aurora Public Schools
 1369 Airport Blvd.
 Aurora, CO 80011

Report Date 4-30-01

Monitor	pCi/l	Installed	Removed	Days Used	pCi/l-days	Tracks	Sq. mm Counted	Notes
931182	1.5	1-2-01	4-12-01	100	148	127	43	Fletcher Elementary - APS - Room #11 <i>Kindergarten</i>
931074	1.3	1-2-01	4-12-01	100	133	116	43	Room #10 <i>Kindergarten</i>
931094	1.5	1-2-01	4-12-01	100	148	127	43	Room #10 <i>Kindergarten</i>
931075	1.3	1-2-01	4-12-01	100	127	112	43	Room #12 <i>Kindergarten</i>
931114	1.2	1-2-01	4-12-01	100	123	109	43	Room #13
931045	1.2	1-2-01	4-12-01	100	123	109	43	Media Center
931025	1.3	1-2-01	4-12-01	100	132	115	43	Media Center
931065	1.5	1-2-01	4-12-01	100	147	126	43	Media Center
931035	1.3	1-2-01	4-12-01	100	130	114	43	Media Center
931123	1.3	1-2-01	4-12-01	100	134	117	43	Computer Lab
931127	1.1	1-2-01	4-12-01	100	111	100	43	Office B1
931084	1.3	1-2-01	4-12-01	100	130	114	43	Room #15 <i>Pre-K</i>
931085	1.6	1-2-01	4-12-01	100	164	138	43	Room #17 <i>Pre-K</i>
931093	1.5	1-2-01	4-12-01	100	151	129	43	Room #16 <i>Pre-K</i>
931104	.9	1-2-01	4-12-01	100	85	82	43	Room #14
931055	1.2	1-2-01	4-12-01	100	116	104	43	Room #14

The uncertainty (standard deviation) of an alpha track radon measurement is $\pm 15\%$.

OK BMS

Radon Environmental Monitoring (ESG)
3334 Commercial Avenue
Northbrook, IL 60062 USA
(847) 205-0110

Mark Davis / Beth Davis
 Aurora Public Schools
 1369 Airport Blvd.
 Aurora, CO 80011

Report Date 4-30-01

Monitor	pCi/l	Installed	Removed	Days Used	pCi/l-days	Tracks	Sq. mm Counted	Notes
931113	1.2	1-2-01	4-12-01	100	120	107	43	Work room A1
931106	1.5	1-2-01	4-12-01	100	148	127	43	Music room

The uncertainty (standard deviation) of an alpha track radon measurement is $\pm 15\%$.